Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: WO/17017UC-0938/1

Work Order Type: Weatherization Audit Name: 17017UC-0938

CLIENT INFORMATION

Client ID: 17017UC-0938

AGENCY INFORMATION

Agency: Upper Cumberland H R A **Agency Phone:** (931) 528-1127

Address: 3313 Williams Enterprise Drive Fax:

Cookeville, TN 38506 **Email Address:**

Agency Contact: Smith, Ron Work Phone: Cell Phone:

Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

1966 SIRE BUILT HOME 1564 SQ. FT.

Measures

Measure 1 Se	eal Ducts			Componen	ts			Inspected
	S: REPAIR 5 DUCT REGIST CAULK INSIDE RETURN							
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Miscellaneous Supplies	Duct Sealing	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Comment INFIL	filtration Redctn TRATION D DOOR AND ALL ASSEM	IBLY		Componen	ts			Inspected
Comment INFIL	TRATION	IBLY		Componen Estimated			Actual	Inspected
Comment INFIL	TRATION	IBLY <i>Unit</i> s	Qty	•		Qty		Inspected Total
Comment INFIL ⁻ PATIC # Material / Labor	TRATION D DOOR AND ALL ASSEM		Qty 1	Estimated	1	Qty	Actual	
Comment INFIL ⁻ PATIC # Material / Labor 10 Miscellaneous	TRATION DOOR AND ALL ASSEM Description / Comment	Units		Estimated	1	Qty	Actual	
# Material / Labor 10 Miscellaneous Supplies	TRATION DOOR AND ALL ASSEM Description / Comment	Units		Estimated	1	Qty	Actual	
# Material / Labor 10 Miscellaneous Supplies	TRATION DOOR AND ALL ASSEM Description / Comment	Units		Estimated	1	Qty	Actual	
# Material / Labor 10 Miscellaneous Supplies	TRATION DOOR AND ALL ASSEM Description / Comment	Units Each	1	Estimated	1		Actual	

	Measure 3 DW	/H Pipe Insulation			Componer	nts			Inspected
C	<i>Johnnent</i>				Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
		wrap water pipes							
2	Labor	DHW Pipe Insulation	Each	1					
(Other Detail						1		
L									
				Measur	e Sub Total:			Sub Total:	
	Measure 4 Atti Comment	ic Ins. R-38			Componer			Actual	Inspected
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Blown Cellulose - R-38	SqFt	1564					
(Other Detail	_							
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Report Run On: 5/20/2010

-	Measure 5 DWI	H Tank Insulation			Componen	its			Inspected
C	omment								
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipment	DHW Tank Insulation	Each	1					
		R-10 minimum-use bubble wrap							
2	Labor	DHW Tank Insulation	Each	1					
C	Other Detail								
				Measur	e Sub Total:] .	Sub Total:	
Γ				mododi	oub rotui.				
	Field Notes:								
	Measure 6 Stor	m Windows			Componen	ts B1,C1	0,C9,C	8,D6,C	Inspected
						4			
C	omment 8 WIND	OWS							
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Windows	Storm Window	SqFt	107.3					
		<99 U.Iea. Under 100 UI							
2	Labor	Storm Window	SqFt	107.3					
3	Other	Storm Window	Each Window	8					
		<99 U.I ea Over 100 UI							
C	Other Detail						1		
				Measure	e Sub Total:			Sub Total:	
	Field Notes:				L				
	rieiu Notes:								

Measure 7 PressureRelief Piping Needed			Components			Inspected			
C	omment								
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Extend T/P Valve to Floor	Each	1					
2	Labor	Labor	Hour	0					
(Other Detail						1		
				Measur	e Sub Total:] ;	Sub Total:	
	Field Notes:								
L									
			Work Or	der Gra	nd Total:		Gran	d Total:	